

Sunday, May 10. 2009

Mac Mini Intel 2.0- Bluetooth issue

I realized sometimes the MacMini get its bluetooth device disable for not reason, being impossible to enable it back. What it looks like the issue is temperature and the internal system fan too slow to properly cool down the box. I found out the following application [smcFanControl](#) which looks like doing the trick, increasing the fan speed , therefore the bluetooth device is present (almost always). It really improved the system

Thanks

Gonza

Posted by Gonzalo in Computing at 17:34